

16 April 1962

STAT

[redacted] Building Planning Staff

STAT

[redacted] Conv. & Tube

Conveyor System

Belts are of a different width than ordered. Belts installed are 3-4 narrower.

Rollers farther apart. System seems to work alright and may be in operation latter part of month.

Tube System

STAT

[redacted]

C System tested but not accepted as yet.

A&B System up in Air - probably 2 months.

STAT

[redacted]